



CHEMICAL HAZARD  
**PICKLING AREA**

**1 Wear nitrile gloves and eye protection**

Pickle solution is acidic. Gloves and safety glasses are mandatory before handling the pot or any work from it.

**2 Never put steel into the pickle pot**

Steel tools contaminate the solution and will copper-plate your work. Use only copper or plastic tongs.

**3 Rinse work thoroughly after pickling**

Remove all acid residue with a full water rinse before returning work to the bench or continuing to solder.

**4 Keep the lid on when not in use**

Replace the pot lid immediately after adding or removing work — reduces fumes and prevents splash accidents.

**5 Skin contact — rinse immediately and notify staff**

Flush affected skin with running water right away. Do not attempt to neutralise alone — find a staff member.

▲ **ACID SOLUTION · NO STEEL TOOLS · RINSE SKIN IMMEDIATELY ON CONTACT**



**JEWELRY & METAL ARTS**  
BELLINGHAM MAKERSPACE