



EXTREME HEAT KILN AREA

- 1 Confirm the correct programme before firing**
Check the schedule is set for your material. Never override or interrupt a programme already running.
- 2 Wear heat-resistant gloves and eye protection**
Kiln gloves and shaded glasses are required when opening the kiln or handling work directly out of it.
- 3 Never reach into a hot kiln without proper tools**
Use kiln tongs or loading forks. Keep face and body clear of the door when opening – heat escapes rapidly.
- 4 Place hot work on the cooling shelf only**
Freshly fired pieces go on the designated cooling shelf – never on the bench, floor, or near flammables.
- 5 Log your firing and sign out**
Record your name, material, programme and end time in the kiln logbook after every use.

▲ SURFACE TEMPERATURES EXCEED 900 °C · DO NOT TOUCH



JEWELRY & METAL ARTS
BELLINGHAM MAKERSPACE