



HAZARDOUS AREA

SOLDERING STATION

- 1 Check ventilation before lighting the torch**
Confirm the fume extractor is on and drawing properly. Never solder without active ventilation running.
- 2 Ignite safely – torch pointing away from your body**
Direct the tip away from yourself and others before striking. Never use matches to light the torch.
- 3 Hot metal looks exactly like cold metal**
Always assume freshly soldered metal is hot. Use cross-locking tweezers or quench in water before handling bare-handed.
- 4 Extinguish the torch whenever you step away**
Stepping away for any reason – even briefly – means the torch goes off completely.
- 5 Cool, clean and clear before you leave**
Quench work, rinse flux residue, wipe the soldering pad and brick, and return all tools to their tray.

▲ FIRE EXTINGUISHER LOCATED BY THE STUDIO DOOR



JEWELRY & METAL ARTS
BELLINGHAM MAKERSPACE