



WORK AREA

## JEWELRY BENCH

- 1 Clear the bench after every session**  
Leave the surface completely clear – no tools, scraps or personal items – so the next maker can start straight away.
- 2 Sweep the surface and bench pin**  
Use the bench brush to sweep all filings and clippings into the bench tray. Never brush onto the floor.
- 3 Wipe out the pull-out drawer**  
Empty metal dust and scraps from the catch drawer and wipe it clean with a dry cloth before you leave.
- 4 Return all tools to their hooks**  
Files, pliers and cutters go back on designated hooks. Bench blocks return to the shelf.
- 5 Check the floor**  
Sweep any dropped pieces – small metal fragments are a hazard for everyone in the studio.

▲ LEAVE IT CLEANER THAN YOU FOUND IT



**JEWELRY & METAL ARTS**  
BELLINGHAM MAKERSPACE